

OSP Cabinet Replacement Fans & Alarm Control Boards




"Litespan High Velocity PDFA"


FTR UPN # TF-LS2000-02
48 Volt Replacement Fan for
Litespan 2000 OSP High Velocity PDFA

(Round Fan)
w/ 3 Wire Connector
(includes plastic rivets)

**HIGH VELOCITY PDFA FAN ASSEMBLY,
FAN TRAY # 509-0000-086 / 509-0000-163**
(fan tray is not included)



NEW Alarm Control Boards
are also available,
order # **TFC-PDFA-01**



Ordering Information:

**48 Volt Replacement Fan for
Litespan 2000 OSP High Velocity PDFA**
(Round Fan) w/ 3 Wire Connector (includes plastic rivets)
(use in High Velocity PDFA Fan Tray # 509-0000-086 / 509-0000-163)

FTR UPN #
TF-LS2000-02

**Alarm Control Board for Litespan 2000
High Velocity PDFA Fan Trays**

TFC-PDFA-01
(call for pricing)

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
Fax : (856) 768-7645

Telecom Assistance Group