
36B Cabinet Solutions for Lumen/CenturyLink

New Replacement Fans, Control Boards & Accessories



Copyright © 2024 by Telecom Assistance Group, Inc.

datasheets\CenturyLink\TAG_36B_Cabinet_Solutions_CLK_r05.dsf (01/17/24)

36B Cabinet Solutions for Lumen/CenturyLink New Replacement Fans, Control Boards & Accessories

Ordering Information: TF-LU2C Lumen/CLK MAT # 1336060	48V Fan for Lucent <u>2C</u> Fan Tray w/ 3 Wire Plug (<i>Equiv. to KS22501L5A</i>) (36B Cabinet, Lucent 2C Tray - Internal)	
TFC-LU2BC-01 Lumen/CLK MAT # 1458909	Alarm Control Board for Lucent 2B & <u>2C</u> Fan Trays (control board only - customer supplied fan trays)	
T-6W3F-05	 Protector / 526A plug to 125 Station Protector (5') - available in various lengths (36B Cabinet, Test Cord - Internal) Cabinet mounting assembly for performing line tests on SLC-96 & Series 5 	125 Station Protector (5) 463A 0 0 526A

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com
Telecom Assistance Group

Telephone: (856) 753-8585 Fax : (856) 768-7645

Copyright © 2024 by Telecom Assistance Group, Inc.

datasheets\CenturyLink\TAG_36B_Cabinet_Solutions_CLK_r05.dsf (01/17/24)