
80 Type / SLC 2000 Cabinet Solutions for Frontier

New Heat Exchanger, Fan & Alarm Control Replacements



Copyright ©2019 by Telecom Assistance Group, Inc.

datasheets/Frontier/TAG_80Type-SLC2000_Cabinet_Solutions_FTR_r06.dsf (10/14/19)

80 Type / SLC 2000 Cabinet Solutions for Frontier

New Heat Exchanger, Fan & Alarm Control Replacements

TR UPN #	48V Heat Exchanger for 80 Type Cabinet	
TF-SLC201-02	w/ Screw on Connector	17-6L-281-62 -197-92: Luka
	(Equiv. to KS23912L4) (80 Type Cabinet - External)	
FTR UPN # TF-SLC201	48V Fan for SLC 2000 4A / 4B Fan Trays w/ 5 Wire Plug	
	(Equiv. to KS23912L6) (80 Type Cabinet, SLC 2000 Tray - Internal)	TF-SLC201 MV DC 8.4.4 CTAG INC. Charling
	(Replacement Power Cables for Lucent 4A/4B Fan Trays are available, order UPN # TFCS-LU4APA-06)	
FC-114A-01	114A Fan Control Unit for 80 Type Cabinet Heat Exchangers (Equiv. to 106894934) (includes metal housing w/ alarm control board)	# TFC-114A-01 # TFC-LU4-01
T <u>R UPN #</u> FC-LU4-01	Alarm Control Board for Lucent 4A/4B, 4G/SLC 2000 Fan Trays & 114A Control Units (control board only - customer supplied fan trays / 114A housing)	
TR UPN # F-SLCBC-01	48V Cooling Fan for 80 Type Cabinet Battery Compartment w/ 3 Wire Plug	# TF-SLCBC-01 # TFC-116A-01
FC-116A-01	Alarm Control Board for Lucent 116A Battery Fan Unit (control board only - customer supplied metal housing)	

W. Berlin, NJ 08091

Telecom Assistance Group

elephone: (856) 753-8585 Fax : (856) 768-7645

Copyright © 2019 by Telecom Assistance Group, Inc.

datasheets/Frontier/TAG_80Type-SLC2000_Cabinet_Solutions_FTR_r06.dsf (10/14/19)