
Mesa 2 Cabinet Solutions for Frontier

New Heat Exchanger & ECU Replacements



150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585 Fax: (856) 768-7645

datasheets\Frontier\TAG_Mesa2_Cabinet_Solutions_FTR_r03.dsf (06/13/19)

Mesa 2 Cabinet Solutions for Frontier

New Heat Exchanger & ECU Replacements

Ordering Information:		
FTR UPN # TF-MC225-01	(225mm) Heat Exchanger for Mesa Cabinet (Top) w/ Round Weatherproof Connector (fan only - use with existing mounting bracket)	
FTR UPN # TF-MC225-02	(225mm) Heat Exchanger for Mesa Cabinet (Bottom) w/ 4 Wire Plug (fan only - use with existing mounting bracket) for Fan with Bracket, order # TF-MC225-02-KIT, Call for Pricing	
TFC-MESA-04	4 Port Environmental Control Unit (ECU) Replacement for Mesa 2 Cabinets used in the DSLAM 192 & DSLAM 384 Type Cabinets	The state of the s

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585 Fax: (856) 768-7645