

# DMS-100 Dual-Scroll Blower Replacement Unit



► **NEW** Drop-in Replacement




## DMS-100 DUAL-SCROLL REPLACEMENT BLOWERS

(used in  
*NT9X950 "w/ hanging blowers"*  
(replaces # A0383325 & A0381714))

### w/ (2) CONNECTORS:

- (1) 4 PIN PLUG  
&  
(1) 3 PIN PLUG\*

\*(includes adapter cable,  
# TFCS-DMSMCL3)



NT9X950  
HAS (3) BLOWER UNITS PER BAY

### Ordering Information:

TF-DMSMCL-02

DMS-100 Dual-Scroll Blower Replacement Unit

**VZ ID #**

7501 3440 (VZ)

1086 2338 (VZB)

w/ (1) 4 pin plug & (1) 3 pin plug

includes (1) 3 pin adapter cable (# TFCS-DMSMCL3) (used in NT9X950 "w/ hanging blowers"  
(replaces # A0383325 & A0381714)) (commonly found in DPCC / LIM / ENET bays)

TFC-DMSAPW-3

Alarm Board for DMS LIM/ENET Blower - (not shown)

150 Cooper Rd. (F-15)

W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

Telephone: (856) 753-8585

Fax : (856) 768-7645

**Telecom Assistance Group**