


## Power Cable Replacement (TYCO CPS 6000 to ALP-448 HX Controller)



Purcell ALP-448 Cabinet HX



### Ordering Information:

TFCS-PURVPWR-05

Power Cable Replacement for OE # HX 1000008379, (two conductor)  
from TYCO CPS 6000 to Purcell ALP-448 Cabinet HX Controller, (5')

Call for Pricing

TFCS-PURVPWR-06

Power Cable Replacement for OE # HX 1000008379, (two conductor)  
from TYCO CPS 6000 to Purcell ALP-448 Cabinet HX Controller, (6')

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)  
**Telecom Assistance Group**

Telephone: (856) 753-8585  
Fax : (856) 768-7645