


# OSP Cabinet Replacement Fans

## "DMS-100 OPM BFU / DMS-1 URBAN"

(Not for use in Nortel Access Node Fan Trays)



UNTERMINATED  
TACH LEAD

CAUTION  
THIS LEAD  
IS LIVE

CAUTION  
THIS LEAD  
IS LIVE

DO NOT  
REMOVE  
UNTIL  
HOOKUP

**WINBUY # TFDMS06**  
48V Replacement Fan for  
**Booster Fan Unit (BFU)** found in  
**DMS-100 OPM Cabinets**

w/ Power Prongs,  
Unterminated Tach Lead  
& (1) Butt Splice

## DMS-100 OPM CABINET BOOSTER FAN UNIT (BFU) w/ EXISTING FANS



Also used in DMS-1  
URBAN EMC RT BAY  
(NT4A44AA fan unit)

### Ordering Information:

**48 Volt Replacement Fan for Booster Fan Unit (BFU)**  
**found in DMS-100 OPM Cabinets**  
w/ Power Prongs, Unterminated Tach Lead & (1) Butt Splice  
(also used in DMS-1 URBAN EMC RT BAY (NT4A44AA fan unit))

**WINBUY #**  
**TFDMS06**

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

Telephone: (856) 753-8585  
Fax : (856) 768-7645

**Telecom Assistance Group**