


OSP Cabinet Replacement Fans & Alarm Control Boards



"Litespan PDFA"


PN # TF-LS2000-01

48 Volt Replacement Fan for
Litespan 2000 Power Distribution (PDFA)


Square Fan w/ 3 Wire Plug & Guard Grill
(includes plastic rivets)

(use in PDFA Fan Tray # 500-1126-723)

NEW Alarm Control Boards
are also available,
order # **TFC-PDFA-X2**



*(2 ALARM CONTROL BOARDS
ARE USED IN EACH TRAY)*



**FAN TRAY # 500-1126-723
w/ (4) EXISTING FANS**

(fan tray is not included)

Ordering Information:

TF-LS2000-01	48 Volt Replacement Fan for LS2000 PDFA, Square Fan w/ 3 Wire Plug & Guard Grill <i>(includes plastic rivets) (use in PDFA Fan Tray # 500-1126-723)</i>	Lumen/CLK MAT # 1341519
TFC-PDFA-X2	Alarm Control Board for LS2000 PDFA Fan Trays <i>(equiv. to # 300-8205-900) (use in PDFA Fan Tray # 500-1126-723)</i>	

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
Fax : (856) 768-7645

Telecom Assistance Group