

OSP Cabinet Replacement Fans & Alarm Control Boards

"Litespan High Velocity PDFA"




PN # TF-LS2000-02
 48 Volt Replacement Fan for
 Litespan 2000 OSP High Velocity PDFA

(Round Fan)
 w/ 3 Wire Connector
 (includes plastic rivets)

HIGH VELOCITY PDFA FAN ASSEMBLY,
FAN TRAY # 509-0000-086 / 509-0000-163
 (fan tray is not included)



NEW Alarm Control Boards
 are also available,
 order # **TFC-PDFA-01**



Ordering Information:

TF-LS2000-02	48 Volt Replacement Fan for Litespan 2000 OSP High Velocity PDFA (Round Fan) w/ 3 Wire Connector <i>(includes plastic rivets)</i> <i>(use in High Velocity PDFA Fan Tray # 509-0000-086 / 509-0000-163)</i>	Lumen/CLK MAT # 1356400
TFC-PDFA-01	Alarm Control Board for Litespan 2000 High Velocity PDFA Fan Trays	

150 Cooper Rd. (F-15)
 W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
 Fax : (856) 768-7645

Telecom Assistance Group