

# OSP Cabinet Replacement Fans & Alarm Control Boards

## "Litespan High Velocity PDFA"

**PN # TF-LS2000-02**


48 Volt Replacement Fan for  
Litespan 2000 High Velocity PDFA

(Round Fan)  
w/ 3 Wire Connector  
(includes plastic rivets)

**HIGH VELOCITY PDFA FAN ASSEMBLY,  
FAN TRAY # 509-0000-086 / 509-0000-163**  
(fan tray is not included)



**NEW** Alarm Control Boards  
are also available,  
order # **TFC-PDFA-01**



### Ordering Information:

		<b>AT&amp;T PID #</b>
<b>TF-LS2000-02</b>	<b>48V Fan for Litespan 2000 High Velocity PDFA (Round Fan) w/ 3 Wire Connector</b> (use in High Velocity PDFA Fan Tray # 509-0000-086 / 509-0000-163)	<b>ATT.200002983</b>
<b>TFC-PDFA-01</b>	<b>Alarm Control Board for Litespan 2000 High Velocity PDFA Fan Trays</b>	<b>ATT.200009332</b>
<b>TFCS-LSPWR-05</b>	<b>Power Cable for Litespan PDFA Controller</b> (not shown) (cable runs from the rectifier to the heat exchanger (pdfa) control boards)	<b>ATT.200012372</b>

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

Telephone: (856) 753-8585  
Fax : (856) 768-7645

**Telecom Assistance Group**