

PowerWorx Front Access Fuse Panel Replacement



PN # TFC-WORX-FAM1
PowerWorx Front Access
Fuse Panel Replacement
(Equiv. to ADC # TFA-FAM)

Used for:

Identification and rework defective alarm circuit board
in the PowerWorx Fuse Panel (PWX-002FGCSD10PWDP)

Issue:

Defective Alarm Circuit Board in the PowerWorx Fuse Panel incorrectly sets remote power alarm. Alarm contact closure has a dead short across normally open and common contacts indicating power distribution or power bus trouble. This problem only affects the ability to monitor local or remote alarms in the ADC PowerWorx distribution panel.

Ordering Information:

TFC-WORX-FAM1 **PowerWorx Front Access Fuse Panel**
(Equiv. to ADC # TFA-FAM)
(used in Remote Cabinet Sites)

AT&T PID #

ATT.200006504

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
Fax : (856) 768-7645

Telecom Assistance Group