

Fan Assembly TAG, Litespan 2000 HV PDFa
(Tray # 509-0000-086 & 509-0000-163)
TFR-LS2000-02

OLD TRAY
Litespan 2000 HV PDFa Fan Tray
(FAN TRAY# 509-0000-086)



Tool and Test Set Repair Ticket

Please complete the form below. If possible, include the Serial Number/Asset Tag of the unit.
The Ship To Address is required. It will be the address that the unit will be returned to.
Upon submission, a shipping label will be generated. This must be included on your return. You will be notified via email when the equipment is received by the Supplier and when the Repair has been completed.

TAG's Fan Assembly refurbishment item is chosen from the dropdown menu

Tool/Test Set	Fan Assembly TAG, Litespan 2000 HV PDFa (Tray # 509-0000-086 & 509-0000-163) TFR-LS2000-02		
Supplier	TAG INC.		
Serial Number			
Asset Tag			
Ship to Address	1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044		Lookup
Manager ATTUID (Who Owns Equipment)	RS781D	Lookup	
Contact ATTUID (To Be Called if Problem)	RS781D		
Problem Category	Other		
Description of Problem	FAN FAIL		
Manufacturer	Alcatel		
Model #	Litespan 2000 HV PDFa		
	Create Ticket	Repair Menu	

TAG is chosen as the supplier

Create Ticket will issue repair # and shipping label

Main Menu | Order Material | My Orders | My Approvals | My Material | Order Status | Reports | Profile | View Cart | Help | Logout | © AT&T Inc.

upFront Tool

Repair Return Label

Once the ticket has been created and submitted, if successful, the user will receive a **Repair Tag Number** and shipping document as shown in the example below.

- Please print **(3) three copies**, this allows the user to keep one, place one inside the box, and place one outside the box when shipping your tool/material for repair.
- Once you have completed printing all of your copies you can exit out of the Repair Return Label screen.

Repair Return Label #135580

Repair Tag:
R735580

Truck Route (GA005A):

Return To
SOPHIA ADAMS
1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044
30044

Telephone
4044996083

Product Description
NOT LISTED: ALL Other Non-Tool/Test Not listed in Category below

Serial Number
123456

Asset Tag
abcde####

RMA

Problem Category
Intermittent Problem

Description of Problem
THE UNIT FAILS TO OPERATE AFTER 5 MINUTES.

SAMPLE



SHIP MATERIAL TO:

TAG, Inc. (Telecom Assistance Group)
150 Cooper Rd. Suite F-15
West Berlin, NJ 08091

Print Date: 7/19/2024 1:39:32 PM
Supplier Website for More Detail: http://www.attsuppliers.com

TAG Refurbishment, Litespan 2000 HV PDFA Fan Tray (TFR-LS2000-02)

OLD TRAY (EMPTY)



TFC-PDFA-01
NEW Alarm Control Board

TF-LS2000-02 (QTY OF 3)
48V Fan Litespan 2000 High Velocity PDFA
w/ 3 Wire Connector



NEW FAN 1




NEW FAN 2



NEW FAN 3

COMPLETED REFURB
WITH ALL NEW FANS,
NEW ALARM CONTROL
BOARD &
WARRANTY LABEL



Tray Refurbished By:

PN: TFR-LS2000-02



TAG INC.

Telecom Assistance Group, Inc.
856-753-8585
www.tagcords.com

SN: 148191

WARRANTY

EXP DATE: 01-14-2023

For questions or additional
information please contact:

Rob Schramm

Regional Sales Manager

(o) 856-753-8585

(c) 856-701-6727

(e) rob@tagcords.com