

Identifying Reltec/McLean SLC APW Fan Trays

(Tray # UJB17H48S22)




TAG Refurbishment, Reltec/McLean SLC APW Fan Tray (TFR-SLCAPW-01)


OLD FAN UNIT (EMPTY)



**# TFC-SLCAPW-4
NEW Alarm Control Board**



**# TF-SLCAPW-01 (QTY OF 4)
48V Fan for SLC 2000 Cabinet -
Reltec / Mclean APW Tray, w/ 3 Wires**



**COMPLETED REFURB
WITH ALL NEW FANS,
NEW ALARM CONTROL BOARD &
WARRANTY LABEL**




Tray Refurbished By: **PN: TFR-SLCAPW-01**
SN: 148194
TAG INC.
Telecom Assistance Group, Inc.
856-753-8585
www.tagcords.com
WARRANTY
EXP DATE: 01-13-2023

**For questions or additional
information please contact:**

Rob Schramm
Regional Sales Manager
(o) 856-753-8585
(c) 856-701-6727
(e) rob@tagcords.com

**Fan Assembly TAG, McLean/Reltec SLC APW
(Tray # UJB17H48S22)
TFR-SLCAPW-01**



Tool and Test Set Repair Ticket

Please complete the form below. If possible, include the Serial Number/Asset Tag of the unit. The Ship To Address is required. **It will be the address that the unit will be returned to.** Upon submission, a shipping label will be generated. This must be included on your return. You will be notified via email when the equipment is received by the Supplier and when the Repair has been completed.

TAG's Fan Assembly refurbishment item is chosen from the dropdown menu

Tool/Test Set	Fan Assembly TAG, McLean/Reltec SLC APW (Tray # UJB17H48S22) TFR-SLCAPW-01	
Supplier	TAG INC.	
Serial Number		
Asset Tag		
Ship to Address	1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044	
Manager ATTUID (Who Owns Equipment)	RS781D	Lookup
Contact ATTUID (To Be Called if Problem)	RS781D	
Problem Category	Other	
Description of Problem	FAN FAIL	
Manufacturer	Reltec/Mclean	
Model #	SLC APW fan tray	
	Create Ticket	Repair Menu

[Main Menu](#) |
 [Order Material](#) |
 [My Orders](#) |
 [My Approvals](#) |
 [My Material](#) |
 [Order Status](#) |
 [Reports](#) |
 [Profile](#) |
 [View Cart](#) |
 [Help](#) |
 [Logout](#)

upFront Tool

Repair Return Label

Once the ticket has been created and submitted, if successful, the user will receive a **Repair Tag Number** and shipping document as shown in the example below.

- Please print **(3) three copies**, this allows the user to keep one, place one inside the box, and place one outside the box when shipping your tool/material for repair.
- Once you have completed printing all of your copies you can exit out of the Repair Return Label screen.

http://procurement05.web.att.com/labelmaker/TestSetsLabel.asp?id=135580 - Internet Explorer provided by AT&T

Repair Return Label #135580

Repair Tag:
R735580

Truck Route (GA005A):

Return To
SOPHIA ADAMS
1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044
30044

Telephone
4044996083

Product Description
NOT LISTED: ALL Other Non-Tool/Test Not listed in Category below

Serial Number
123456

Asset Tag
abcde####

RMA

Problem Category
Intermittent Problem

Description of Problem
THE UNIT FAILS TO OPERATE AFTER 5 MINUTES.

SHIP MATERIAL TO:

TAG, Inc. (Telecom Assistance Group)
150 Cooper Rd. Suite F-15
West Berlin, NJ 08091

Print Date: 7/19/2024 1:39:32 PM
Supplier Website for More Detail: <http://www.attsuppliers.com>