



# Carrier VoIP Replacement Fans



**FTR UPN # TF-DMS-FOS**  
**Nortel IW SPM-IP**  
48 Volt Replacement Fan  
for **NTLX56AA**  
fan assemblies\*

(used in Nortel IW SPM-IP NTLX55AA cooling units)

\* fan only, arm assembly is not included



← PN # TF-DMS-FOS



←  
**FRONT VIEW OF**  
**NTLX56AA FAN ASSEMBLY**  
(NOT SUPPLIED)

## Ordering Information:

**Nortel IW SPM-IP 48 Volt Replacement Fan**  
for **NTLX56AA** Fan Assemblies

(used in Nortel IW SPM-IP NTLX55AA cooling units) (fan only, arm assembly is not included)

**FTR UPN #**  
**TF-DMS-FOS**

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

Telephone: (856) 753-8585  
Fax: (856) 768-7645

**Telecom Assistance Group**