


OSP Cabinet Replacement Fans & Alarm Control Boards



"Litespan PDFA"


FTR UPN # TF-LS2000-01

48 Volt Replacement Fan for
Litespan 2000 Power Distribution (PDFA)


Square Fan w/ 3 Wire Plug & Guard Grill
(includes plastic rivets)

(use in PDFA Fan Tray # 500-1126-723)

NEW Alarm Control Boards
are also available,
order # **TFC-PDFA-X2**



*(2 ALARM CONTROL BOARDS
ARE USED IN EACH TRAY)*



**FAN TRAY # 500-1126-723
w/ (4) EXISTING FANS**

(fan tray is not included)

Ordering Information:

**48 Volt Replacement Fan for LS2000 PDFA,
Square Fan w/ 3 Wire Plug & Guard Grill**
(includes plastic rivets) (use in PDFA Fan Tray # 500-1126-723)

FTR UPN #

TF-LS2000-01

Alarm Control Board for LS2000 PDFA Fan Trays
(equiv. to # 300-8205-900) (use in PDFA Fan Tray # 500-1126-723)

TFC-PDFA-X2

(call for pricing)

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
Fax : (856) 768-7645

Telecom Assistance Group