



OSP Cabinet Replacement Fans



(TOP VIEW)



**LUCENT 2A FAN TRAY
HAS (3) FANS (INSIDE VIEW)**
(fan tray is not included)



**THERE ARE TWO TYPES
of 2A FAN TRAYS (BLUE / TAN)**
(INSIDE VIEW of 80A/D CABINET)

Ordering Information:

**48 Volt Replacement Fan for Lucent 2A Fan Tray
w/ 3 Leads & Faston Connectors**
(fan only, use with existing guard grills) (Equiv. to KS22501L5)

FTR UPN #

TF-LU2A

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585

Fax : (856) 768-7645

Telecom Assistance Group