


OSP Cabinet Replacement Fans & Alarm Control Boards



INSIDE VIEW OF 80A/D CABINET



"Lucent 2B / 2C"

FTR UPN # TF-LU2B
 48 Volt Replacement Fan for
Lucent 2B Fan Tray
 w/ 3 Wire Plug
 (Equiv. to KS22501L5A)

NEW Alarm Control Boards are also available,
 order **FTR UPN # TFC-LU2BC-01**



LUCENT 2B FAN TRAY
 w/ (3) EXISTING FANS (BOTTOM VIEW)
 (fan tray is not included)

Ordering Information:

48 Volt Replacement Fan for Lucent 2B Fan Tray
 w/ 3 Wire Plug (Equiv. to KS22501L5A)

FTR UPN #

TF-LU2B

48 Volt Replacement Fan for SLC5 Cabinet 2B Fan Tray (not shown)
 w/ 3 Wire Plug (Equiv. to KS22501L5A)

TF-SLC5-01

48 Volt Replacement Fan for Lucent 2C Fan Tray (not shown)
 w/ 3 Wire Plug (Equiv. to KS22501L5A)

TF-LU2C
 (call for pricing)

Alarm Control Board Replacement for Lucent 2B & 2C Fan Trays
 (customer supplied fan trays)

TFC-LU2BC-01

150 Cooper Rd. (F-15)
 W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
 Fax : (856) 768-7645

Telecom Assistance Group