

# OSP Cabinet Replacement Fans & Alarm Control Boards

## "Lucent 4A / 4B"

### **FTR UPN # TF-SLC201**

48 Volt Replacement Fan for  
SLC 2000 4A / 4B Fan Trays



w/ 5 Wire Plug

*(Equiv. to KS23912L6)*


*(80 Type Cabinet,  
SLC 2000 Tray - Internal)*



**SLC 2000 EQUIPMENT -  
4B FAN UNIT w/ (2) FANS**  
*(fan tray is not included)*



**NEW** Alarm Control Boards  
are also available, order  
**FTR UPN # TFC-LU4-01**



### **Ordering Information:**

**48V Fan w/ 5 Wire Plug for SLC 2000 4A / 4B Fan Trays**  
*(Equiv. to KS23912L6) (80 Type Cabinet, SLC 2000 Tray - Internal)*

**Alarm Control Board Replacement for 4A/4B,  
4G/SLC 2000 Trays & 114A Control Units**  
*(control board only - customer supplied fan trays / 114A housing)*

### **FTR UPN #**

**TF-SLC201**

**TFC-LU4-01**

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

Telephone: (856) 753-8585

Fax : (856) 768-7645

**Telecom Assistance Group**