OSP Cabinet Replacement Fans

"SLC96 (36 Type) Cabinet"

PN # TFT-SLC96-AC01

110VAC Replacement Fan w/ Bracket Assembly for SLC96 (36 Type) Cabinet

(Equiv. to Fan Assembly KS22099L5)

(1) 110VAC Replacement Fan *

* fans can also be ordered separately (without mounting), see ordering information below

&

(1) Mounting Bracket



FAN ASSEMBLY IS FOUND INSIDE 36 TYPE CABINETS



Ordering Information:

TFT-SLC96-AC01 110VAC Fan w/ Bracket Assembly for

SLC96 (36 Type) Cabinet (Equiv. to Fan Assembly KS22099L5)

TFT-SLC96-AC01L 110VAC (Low Temp) Fan w/ Bracket Assembly for

SLC96 (36 Type) Cabinet (Equiv. to Fan Assembly KS22099L5)

TF-SLC96-AC02 110VAC Fan (fan only) for SLC96 (36 Type) Cabinet

(fan only) (includes power wire, (3) butt splices & hardware)

(use in Fan Assembly KS22099L5)

Telephone: (856) 753-8585

Fax: (856) 768-7645

AT&T PID # ATT.200008234

ATT.200008235

ATT.200004398

Telecom Assistance Group

Copyright © 2020 by Telecom Assistance Group, Inc.

150 Cooper Rd. (F-15)

W. Berlin, NJ 08091

datasheets\AT&T\TFT-SLC96-AC01 TF-SLC96-AC02 ATT r04.dsf (08/11/20)