



Application:

TAG's BNC-G102 verifies BNC plug center pin depth.

The BNC-G102 is ideal to check BNC cable terminations assembled in the field.

1. Insert the Calibration Plug into the gauge - verify 0.
2. Plug active BNC plug into gauge - verify +/- 10.

Ordering Information:

BNC-G102

BNC Center Pin Depth Gauge

Call for Pricing

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585

Fax : (856) 768-7645