


# Alcatel 1631\* Replacement Fans

**PN # TF-ALC1631-01**  
 48V Replacement Fan for  
**Alcatel 1631 Blower Assembly**  
 w/ Power Prongs  
*(fan is equiv. to MD48B2)*



## "Alcatel 1631"



*(fan only -  
 use with  
 existing  
 guard grill)*

← **# 695-3363-302 (w/ 3 EXISTING FANS)**  
*(blower assembly is not included)*

## "Alcatel 1631"

*(fan only -  
 use with  
 existing  
 guard grill)*




**PN # TF-ALC1631-02**  
 48V Replacement Fan for  
**Alcatel 1631 Blower Assembly**  
 w/ Power Prongs,  
 Unterminated Tach Lead & (1) Butt Splice  
*(fan is equiv. to PQ48S4HNDNX)*



**# 3AL45446AA (w/ 3 EXISTING FANS)**  
*(blower assembly is not included)*


**PN # TF-ALC1631-03**  
 48V Replacement Fan for  
**Alcatel 1631 APS Blower Assembly**  
 w/ Power Prongs & Unterminated Tach Lead  
*(fan is equiv. to MD48B2NDNX)*



## "Alcatel 1631"



*(fan only -  
 use with existing  
 guard grill)*



← **# 695-8489-001 (w/ 3 EXISTING FANS)**  
*(blower assembly is not included)*

150 Cooper Rd. (F-15)  
 W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

Telephone: (856) 753-8585  
 Fax : (856) 768-7645

**Telecom Assistance Group**