

# DMS-100 Dual-Scroll Blower Replacement Unit



► **NEW** Drop-in Replacement

**DMS-100 DUAL-SCROLL  
REPLACEMENT BLOWERS**





(used in  
NT9X950 "w/ hanging blowers"  
(replaces # A0383325 & A0381714))

(Commonly found in  
DPCC / LIM / ENET bays)

**w/ (2) CONNECTORS:**

(1) 4 PIN PLUG  
&  
(1) 3 PIN PLUG\*

\*(includes adapter cable,  
# TFCS-DMSMCL3)



**NT9X950  
HAS (3) BLOWER UNITS PER BAY**

## Ordering Information:

**TF-DMSMCL-02**

**DMS-100 Dual-Scroll Blower Replacement Unit  
w/ (1) 4 pin plug & (1) 3 pin plug**

includes (1) 3 pin adapter cable (# TFCS-DMSMCL3) (used in NT9X950 "w/ hanging blowers"  
(replaces # A0383325 & A0381714)) (commonly found in DPCC / LIM / ENET bays)

**TFC-DMSAPW-3**

**Alarm Board for DMS LIM/ENET Blower - (not shown)**

**Brightspeed SAP MAT #**

**1490298**

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

Telephone: (856) 753-8585  
Fax : (856) 768-7645

**Telecom Assistance Group**