




Mesa 768 Cabinet Solutions for Lumen/CenturyLink

New Heat Exchanger Replacements



MOUNTING BRACKET
LOCATED ON THE ROOF
OF THE CABINET




MESA 768 CABINET (FRONT VIEW)

MESA 768 CABINET (INSIDE - FRONT VIEW)

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com
Telecom Assistance Group

Telephone: (856) 753-8585
Fax : (856) 768-7645



(133mm)

TAG # TF-MC133-02

(NEW 133mm
Heat Exchanger)

Lumen/CLK MAT # 1355448

(1) IN EACH
CABINET

TAG Inc. - (REPAIRS)
MARCONI / RELTEC / TELLABS
POWER CONTROL UNITS (PCU's)



- Trace Circuitry Testing & Repair
- Component Testing & Replacement

For more Information,
Please Call:
856-753-8585

or Email:
custsvcs@tagcords.com

Ordering Information:

TF-MC133-02

**Lumen/CLK MAT #
1355448**

**(133mm) Heat Exchanger for Mesa 768 Cabinets
w/ 3 Pin Plug**

*(Equiv. to Diplomat DC, P/N 031794,
Model # DDF48B6NDX)*

(fan only - use with existing mounting bracket)



150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com
Telecom Assistance Group

Telephone: (856) 753-8585
Fax : (856) 768-7645