


80 Type / SLC 2000 Cabinet Solutions for Windstream

New Heat Exchangers, Fans & Alarm Control Replacements

Heat Exchangers

TAG # TF-SLC201-02
(NEW Heat Exchanger)




(2) MOUNTED ON CABINET SIDE (TOP & BOTTOM)



WINBUY # TFCLU401
(NEW Alarm Control Board)

(1) ALARM BOARD PER TRAY

4A / 4B Fan Trays




WINBUY # TFSLC201 (NEW 48V Fan)


(2) FAN TRAYS SHOWN IN THIS CABINET (4 FANS TOTAL)

Fans are shown installed in existing fan tray, **the tray IS NOT included**

(NEW Power Cables for 4A/4B Fan Trays are available, order # TFC-S-LU4APA-06)



116A Control Unit (Battery)
- reverse side of cabinet



116A Control Board

TAG # TF-SLCBC-01
(NEW Battery Cooling Fan)
(1) FAN PER CABINET



TAG # TFC-116A-01
(NEW Alarm Control Board for Lucent 116A Battery Unit)
(1) PER CABINET

80 TYPE CABINET (INSIDE VIEW)

114A Control Unit



TAG # TFC-114A-01*
(NEW Heat Exchanger Control Unit)












** if metal housing is not needed, order **WINBUY # TFCLU401***

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com
Telecom Assistance Group

Telephone: (856) 753-8585
Fax: (856) 768-7645

Ordering Information:

<p>TF-SLC201-02 <i>(call for pricing)</i></p>	<p>48V Heat Exchanger for 80 Type Cabinet w/ Screw on Connector <i>(Equiv. to KS23912L4)</i> <i>(80 Type Cabinet - External)</i></p>	 
<p>WINBUY # TFSLC201</p>	<p>48V Fan for SLC 2000 4A / 4B Fan Trays w/ 5 Wire Plug <i>(Equiv. to KS23912L6)</i> <i>(80 Type Cabinet, SLC 2000 Tray - Internal)</i> <i>(Replacement Power Cables for Lucent 4A/4B Fan Trays are available, order # TFCS-LU4APA-06)</i></p>	 
<p>TFC-114A-01 <i>(call for pricing)</i></p>	<p>114A Fan Control Unit Replacement for 80 Type Cabinet Heat Exchangers <i>(Equiv. to 106894934)</i> <i>(includes metal housing w/ alarm control board)</i></p>	<p># TFC-114A-01</p>  <p>WINBUY # TFCLU401</p> 
<p>WINBUY # TFCLU401</p>	<p>Alarm Control Board Replacement for Lucent 4A/4B, 4G/SLC 2000 Fan Trays & 114A Control Units <i>(control board only - customer supplied fan trays / 114A housing)</i></p>	<p># TF-SLCBC-01</p>  <p># TFC-116A-01</p>  
<p>TF-SLCBC-01 <i>(call for pricing)</i></p>	<p>48V Cooling Fan for 80 Type Cabinet Battery Compartment w/ 3 Wire Plug</p>	<p># TFC-116A-01</p> 
<p>TFC-116A-01 <i>(call for pricing)</i></p>	<p>Alarm Control Board for Lucent 116A Battery Fan Unit <i>(control board only - customer supplied metal housing)</i></p>	

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585

Fax : (856) 768-7645