




Carrier VoIP Replacement Fans



PN # TF-DMS-FOS
Nortel IW SPM-IP
48 Volt Replacement Fan
 for **NTLX56AA**
 fan assemblies*

(used in **Nortel IW SPM-IP NTLX55AA** cooling units)

* fan only, arm assembly is not included



← PN # TF-DMS-FOS



←
FRONT VIEW OF
NTLX56AA FAN ASSEMBLY
 (NOT SUPPLIED)

Ordering Information:

TF-DMS-FOS

Nortel IW SPM-IP 48 Volt Replacement Fan
for NTLX56AA Fan Assemblies
 (used in Nortel IW SPM-IP NTLX55AA cooling units)
 (fan only, arm assembly is not included)

Lumen/CLK MAT #

1341507

150 Cooper Rd. (F-15)
 W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
 Fax: (856) 768-7645

Telecom Assistance Group