



OSP Cabinet Replacement Fans & Alarm Control Boards



LUCENT 2C FAN TRAY
IN MESA TYPE CABINET
(fan tray is not included)




AIRFLOW DIRECTION POINTS UP

"Lucent 2C"

PN # TF-LU2C
48 Volt Replacement Fan for
Lucent 2C Fan Tray
w/ 3 Wire Plug
(Equiv. to KS22501L5A)

NEW Alarm Control Boards
are also available, order
TFC-LU2BC-01, MAT # 1458909



Ordering Information:

		<u>Lumen/CLK MAT #</u>
TF-LU2C	48V Fan for Lucent 2C Fan Tray w/ 3 Wire Plug <i>(Equiv. to KS22501L5A)</i>	1336060
TFC-LU2BC-01	Alarm Control Board for Lucent 2B & 2C Fan Trays <i>(customer supplied fan trays)</i>	1458909
TFCS-2BPWRY-01	Power Cable "Y" for Lucent 2B & 2C Fan Trays <i>w/ 1 Male Connector to Female "Y", (1') - (not shown)</i>	
TFCS-2BRS-08	Remote Sensing Daisy Chain Cable for Lucent 2B & 2C Fan Trays <i>w/ 2 Wires & Connectors, (8') - (not shown)</i>	

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
Fax : (856) 768-7645

Telecom Assistance Group