

OSP Cabinet Replacement Fans & Alarm Control Boards

"Lucent 4A / 4B"

PN # TF-SLC201

48 Volt Replacement Fan for
SLC 2000 4A / 4B Fan Trays


w/ 5 Wire Plug

(Equiv. to KS23912L6)

*(80 Type Cabinet,
SLC 2000 Tray - Internal)*



**SLC 2000 EQUIPMENT -
4B FAN UNIT w/ (2) FANS**
(fan tray is not included)



NEW Alarm Control Boards
are also available,
order #TFC-LU4-01,
Lumen/CLK MAT # 1355244



Ordering Information:

Lumen/CLK MAT

TF-SLC201	48V Fan w/ 5 Wire Plug for SLC 2000 4A / 4B Fan Trays <i>(Equiv. to KS23912L6) (80 Type Cabinet, SLC 2000 Tray - Internal)</i>	1336047
TFC-LU4-01	Alarm Control Board Replacement for 4A/4B, 4G/SLC 2000 Trays & 114A Control Units <i>(control board only - customer supplied fan trays / 114A housing)</i>	1355244

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585

Fax : (856) 768-7645

Telecom Assistance Group