

# Lucent 2B Fan Unit (TFR-LU2B-01)

**Part Number** ▼

SAP Material Code:       Manufacturer Part Nbr:       Part Description:

HECI:

**STEP 2**

**After STEP 1 and STEP 2:**  
 Manufacturer Part Nbr and Part Description will be auto populated.  
*Note: Disregard inactive or deleted in Part Description*

**Ship Details** ▼

From Address:

From Zip:

Serial Nbr:

**STEP 3: Fill in Ship Details**

Vendor Name:

From City:

Contact Name:

Equipment Error:

Vendor Nbr:

From State:

Contact Nbr:

Tracking Number:

**STEP 4:** Click "Create" to Generate a Shipping Label



**SHIPPING LABEL**



**OLD TRAY**  
 Lucent 2B Fan Unit  
 (COMCODE: 105550420)



**DEFECTIVE / IN ALARM**

# Lucent 2B Fan Unit (TFR-LU2B-01)

**OLD FAN UNIT (EMPTY)**



**# TFC-LU2BC-01  
NEW Alarm Control Board**

**# TF-LU2B (QTY OF 3)  
48V Fan for Lucent 2B Fan Unit  
w/ 3 Wire Plug**



**NEW  
FAN 1**




**NEW  
FAN 2**



**NEW  
FAN 3**

**COMPLETED REFURB  
WITH ALL NEW FANS,  
NEW ALARM CONTROL BOARD &  
WARRANTY LABEL**



Tray Refurbished By:	PN: TFR-LU2B-01
 <b>TAG INC.</b> Telecom Assistance Group, Inc. 856-753-8585 www.tagcords.com	SN: 148193
	WARRANTY EXP DATE: 07-15-2022

*For questions or additional information please contact:*

**Rob Schramm**  
Regional Sales Manager  
(o) 856-753-8585  
(c) 856-701-6727  
(e) [rob@tagcords.com](mailto:rob@tagcords.com)

# Identifying Lucent 2B Fan Units

(COMCODE: 105550420)

