OSP Cabinet Heat Exchanger Fans



"Telamon / Ciena 5150"

PN # TF-CN5150HX-01


48V Replacement Heat Exchanger for Telamon / Ciena 5150 EMUX Cabinet Door

w/ 4 Wires & Sealed Connector

(8) HEAT EXCHANGERS
ARE MOUNTED IN THE DOOR
OF THE CABINET



TELAMON / CIENA 5150 CABINET



Ordering Information:

AT&T PID#

TF-CN5150HX-01 48V R

48V Replacement Heat Exchanger for Telamon / Ciena 5150 EMUX Cabinet Door

w/ 4 Wires & Sealed Connector

ATT.200008097

150 Cooper Rd. (F-15) W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585

Fax: (856) 768-7645

Telecom Assistance Group