

Identifying Alcatel 7330 VRAD Fan Units




(3FE 24322 (XXXX) (HECI:VAPQAFZFAC, VAPQAFZFAB, VAPQAFZFAD, VAPQAFZFAD))



TAG Refurbishment, Alcatel 7330 VRAD Fan Unit (TFR-ALC7330-01)

OLD FAN UNIT (EMPTY)



TF-ALC7330-4

**(4) 48V Fans w/ Guard Grills &
Wiring Harness w/ Hardwired DB15F**



**COMPLETED REFURB
WITH ALL NEW FANS,
WIRING HARNESS &
WARRANTY LABEL**



Tray Refurbished By:



PN: TFR-ALC7330-01

SN: 148193

WARRANTY

EXP DATE: 01-13-2023

*For questions or additional
information please contact:*

Rob Schramm

Regional Sales Manager

(o) 856-753-8585

(c) 856-701-6727

(e) rob@tagcords.com

Fan Assembly TAG, Alcatel 7330 VRAD
(HECI: VAPQAFZFxx) (3FE 24322 (XXXX))
TFR-ALC7330-01

OLD TRAY
7330 VRAD Fan Tray
(3FE 24322 (XXXX) (HECI:VAPQAFZFxx),
VAPQAFZFAB, VAPQAFZFAC, VAPQAFZFAD)



Tool and Test Set Repair Ticket

Please complete the form below. If possible, include the Serial Number/Asset Tag of the unit.
The Ship To Address is required. It will be the address that the unit will be returned to.
Upon submission, a shipping label will be generated. This must be included on your return. You will be notified via email when the equipment is received by the Supplier and when the Repair has been completed.

TAG's Fan Assembly refurbishment item is chosen from the dropdown menu

Tool/Test Set

Supplier

Serial Number

Asset Tag

Ship to Address

Manager ATTUID (Who Owns Equipment)

Contact ATTUID (To Be Called if Problem)

Problem Category

Description of Problem

Manufacturer

Model #

Fan Assembly TAG, Alcatel 7330 VRAD (HECI: VAPQAFZFxx) (3FE 24322 (XXXX) TFR-ALC7330-01

TAG INC.

1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044

RS781D

RS781D

Other

FAN FAIL

Alcatel

7330 VRAD fan tray

Create Ticket

Repair Menu

Lookup

Lookup

Create Ticket will issue repair # and shipping label

upFront Tool

Repair Return Label
Once the ticket has been created and submitted, if successful, the user will receive a **Repair Tag Number** and shipping document as shown in the example below.

- Please print **(3) three copies**, this allows the user to keep one, place one inside the box, and place one outside the box when shipping your tool/material for repair.
- Once you have completed printing all of your copies you can exit out of the Repair Return Label screen.

Repair Return Label #135580

Repair Tag: R735580

Truck Route (GA005A):

Return To

Telephone

Product Description

Serial Number

Asset Tag

RMA

Problem Category

Description of Problem

SHIP MATERIAL TO:

Print Date: 7/19/2024 1:39:32 PM

Supplier Website for More Detail: http://www.attsuppliers.com

Barcode

Barcode

SOPHIA ADAMS

1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044

4044996083

NOT LISTED: ALL Other Non-Tool/Test Not listed in Category below

123456

abcde####

Intermittent Problem

THE UNIT FAILS TO OPERATE AFTER 5 MINUTES.

TAG, Inc. (Telecom Assistance Group)

150 Cooper Rd. Suite F-15

West Berlin, NJ 08091

SAMPLE