


## Identifying Lucent 2A Fan Units

2 versions of the 2A (blue or tan)




# TAG Refurbishment, Lucent 2A Fan Unit (TFR-LU2A-01)

**OLD FAN UNIT (EMPTY)**



**NEW Alarm  
Control Board**



**# TF-LU2A (QTY OF 3)  
48V Fan for Lucent 2A Fan Tray**



**NEW FAN 1**




**NEW FAN 2**



**NEW FAN 3**

**COMPLETED REFURB  
WITH ALL NEW FANS,  
NEW ALARM CONTROL BOARD &  
WARRANTY LABEL**



Tray Refurbished By: **TAG INC.**  
Telecom Assistance Group, Inc.  
856-753-8585  
www.tagcords.com

PN: TFR-LU2A-01  
SN: 148194  
WARRANTY  
EXP DATE: 03-22-2024

**For questions or additional  
information please contact:**

**Rob Schramm**  
Regional Sales Manager  
(o) 856-753-8585  
(c) 856-701-6727  
(e) [rob@tagcords.com](mailto:rob@tagcords.com)



Fan Assembly TAG, 2A Lucent Fan Tray TFR-LU2A-01



Tool and Test Set Repair Ticket

Please complete the form below. If possible, include the Serial Number/Asset Tag of the unit. The Ship To Address is required. **It will be the address that the unit will be returned to.** Upon submission, a shipping label will be generated. This must be included on your return. You will be notified via email when the equipment is received by the Supplier and when the Repair has been completed.

Tool/Test Set

Fan Assembly TAG, 2A Lucent Fan Tray TFR-LU2A-01

Supplier

TAG INC.

Serial Number

Asset Tag

Ship to Address

1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044

Lookup

Manager ATTUID (Who Owns Equipment)

RS781D

Lookup

Contact ATTUID (To Be Called if Problem)

RS781D

Problem Category

Other

Description of Problem

FAN FAIL

Manufacturer

Lucent

Model #

2A fan tray

Create Ticket

Repair Menu

TAG's Fan Assembly refurbishment item is chosen from the dropdown menu

TAG is chosen as the supplier

Create Ticket will issue repair # and shipping label

Main Menu

Order Material

My Orders

My Approvals

My Material

Order Status

Reports

Profile

View Cart

Help

Logout

© AT&T Inc.

upFront Tool

**Repair Return Label**  
Once the ticket has been created and submitted, if successful, the user will receive a **Repair Tag Number** and shipping document as shown in the example below.

- Please print **(3) three copies**, this allows the user to keep one, place one inside the box, and place one outside the box when shipping your tool/material for repair.
- Once you have completed printing all of your copies you can exit out of the Repair Return Label screen.

Repair Return Label #135580

Repair Tag: R735580

Truck Route (GA005A):

Return To SOPHIA ADAMS  
1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044  
30044

Telephone 4044996083

Product Description NOT LISTED: ALL Other Non-Tool/Test Not listed in Category below

Serial Number 123456

Asset Tag abcde####

RMA

Problem Category Intermittent Problem

Description of Problem THE UNIT FAILS TO OPERATE AFTER 5 MINUTES.

SHIP MATERIAL TO:

TAG, Inc. (Telecom Assistance Group)  
150 Cooper Rd. Suite F-15  
West Berlin, NJ 08091

Print Date: 7/19/2024 1:39:32 PM  
Supplier Website for More Detail: http://www.attsuppliers.com

AT&T is a registered ® trademark

TFR-LU2A-01\_ATT\_r05.xlsx